

# Inspection Photos

June 10, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 313327

Location Name: Saratoga-67N93W /3SESE

Inspection Document #: 702800334

Moffat County, CO

SESE Section 3 T7N R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Saratoga-67N93W /3SESE  
Location ID: 313327



**Photo 1.** Photo taken from the south of the Location shows an overview of the Location.



**Photo 2.** Photo taken from the northeast of the Location shows an overview of the Location.



Inspection Photos  
Location Name: Saratoga-67N93W /3SESE  
Location ID: 313327



**Photo 3.** Photo taken from the south of the Location shows risers, pipes and power lines which must be removed for final reclamation per Rule 1004.a.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800334



Inspection Photos  
Location Name: Saratoga-67N93W /3SESE  
Location ID: 313327



**Photo 4.** Photo taken from the southeast of the Location shows berms associated with stormwater BMPs which must be removed along with ditches to pass final reclamation.



**Photo 5.** Photo taken from the southeast of the Location shows an impoundment which must be removed and contoured to match the surrounding landscape to pass final reclamation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800334



Inspection Photos  
Location Name: Saratoga-67N93W /3SESE  
Location ID: 313327



**Photo 6.** Photo taken from the east of the Location shows Scotch thistle, a noxious weed.



**Photo 7.** Photo taken from the center of the Location shows a pile of stone which must be removed for final reclamation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800334



Inspection Photos  
Location Name: Saratoga-67N93W /3SESE  
Location ID: 313327



**Photo 8.** Photo taken from the north of the Location shows adjacent reference area vegetation.

