

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403076778

Date Received:

06/15/2022

Spill report taken by:

CHESSON, BOB

Spill/Release Point ID:

482372

## SPILL/RELEASE REPORT (INITIAL /w SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

### OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL &amp; GAS ONSHORE LP</u>	Operator No: <u>47120</u>	<b>Phone Numbers</b>
Address: <u>P O BOX 173779</u>		Phone: <u>(970) 336-3500</u>
City: <u>DENVER</u>	State: <u>CO</u>	Mobile: <u>(970) 515-1698</u>
Zip: <u>80217-3779</u>		Email: <u>gregory_hamilton@oxy.com</u>
Contact Person: <u>Gregory Hamilton</u>		

☐ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 403076778

Initial Report Date: 06/13/2022 Date of Discovery: 06/13/2022 Spill Type: Historical Release

#### Spill/Release Point Location:

QTRQTR NWNE SEC 6 TWP 2N RNG 65W MERIDIAN 6Latitude: 40.172926 Longitude: -104.703949Municipality (if within municipal boundaries): \_\_\_\_\_ County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

#### Reference Location:

Facility Type: WELL☐ Facility/Location ID No \_\_\_\_\_Spill/Release Point Name: Lee 25-6X wellhead☒ Well API No. (Only if the reference facility is well) 05-123-33287☐ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): UnknownEstimated Condensate Spill Volume(bbl): UnknownEstimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): UnknownEstimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

Has the subject Spill/Release been controlled at the time of reporting? Yes

#### Land Use:

Current Land Use: CROP LAND

Other(Specify): \_\_\_\_\_

Weather Condition: Partly Cloudy, ~89 degrees FSurface Owner: FEE

Other(Specify): \_\_\_\_\_

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On June 13, 2022, historical soil impacts were discovered following cut and cap operations at the Lee 25-6X wellhead location. Excavation and assessment activities are ongoing. A topographic Site Location Map showing the geographic setting of the release is provided as Figure 1.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
6/13/2022	Landowner	Private	-phone	
6/13/2022	Weld County	J. Maxey	-email	
6/13/2022	Weld County	R. Rudisill	-email	

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

No	Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.  Waters of the State: _____ Public Water System: _____ Residence or Occupied Structure: _____ Livestock: _____ Wildlife: _____ Publicly-Maintained Road: _____
No	Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.
No	Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.
No	Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak  Enter the approximate time of discovery _____ (HH:MM) Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 _____ Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? _____ Enter the Document Number of the Initial Accident Report, Form 22 _____ Was there damage during excavation? _____ Was CO 811 notified prior to excavation? _____
Yes	Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.  Estimated Volume of Impacted Solids (cu. yd.): _____ 10
No	Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:  <input type="checkbox"/> The presence of free product or hydrocarbon sheen Surface Water <input type="checkbox"/> The presence of free product or hydrocarbon sheen on Groundwater <input type="checkbox"/> The presence of contaminated soil in contact with Groundwater <input type="checkbox"/> The presence of contaminated soil in contact with Surface water

Yes	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylights from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.
	<input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

## SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 06/13/2022		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL			<input checked="" type="checkbox"/>
CONDENSATE			<input checked="" type="checkbox"/>
PRODUCED WATER			<input checked="" type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, <b>including walls &amp; floor regardless of construction material</b>, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): <u>16</u>		Width of Impact (feet): <u>16</u>	
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____	
How was extent determined?			
Following cut and cap operations at the Lee 25-6X wellhead location on June 10, 2022, confirmation soil samples were collected from the former wellhead and submitted for laboratory analysis of the full COGCC Table 915-1 suite using COGCC-approved methods appropriate for detecting the target analytes. Preliminary analytical results received on June 13, 2022, indicate that the benzene, 1,2,4-trimethylbenzene (TMB), and 1,3,5-TMB concentrations in soil sample WH-B05@5' at the former Lee 25-6X wellhead exceeded the applicable COGCC Table 915-1 Protection of Groundwater Soil Screening Level Cleanup Concentrations. Assessment activities are ongoing and will be summarized in a forthcoming quarterly Form 27-Supplemental Site Investigation and Remediation Workplan under Remediation Project No. 23136 (approved Form 27 Document No. 403045262). A topographic Site Location Map showing the geographic setting of the release is provided as Figure 1. The soil sample locations are illustrated on Figure 2. Soil sample location and field screening data are provided in Table 1. Soil analytical results are summarized in Table 2. The preliminary laboratory analytical report is provided as Attachment A. Field notes and a photographic log are provided as Attachment B. The State Notification email is provided as Attachment C.			
Soil/Geology Description:			
Well-graded Sand (SW)			
Depth to Groundwater (feet BGS) <u>15</u>		Number Water Wells within 1/2 mile radius: <u>3</u>	
If less than 1 mile, distance in feet to nearest	Water Well <u>1565</u>	None <input type="checkbox"/>	Surface Water <u>4371</u> None <input type="checkbox"/>
	Wetlands <u>2915</u>	None <input type="checkbox"/>	Springs _____ None <input checked="" type="checkbox"/>
	Livestock _____	None <input checked="" type="checkbox"/>	Occupied Building <u>1202</u> None <input type="checkbox"/>
Additional Spill Details Not Provided Above:			

## CORRECTIVE ACTIONS

#1 Supplemental Report Date: 06/13/2022

Root Cause of Spill/Release Unknown (Historical)

Other (specify)

Type of Equipment at Point of Spill/Release: Other

If "Other" selected above, specify or describe here:

Wellhead

Describe Incident & Root Cause (include specific equipment and point of failure)

Historical impacts were discovered following cut and cap operations at the wellhead.

Describe measures taken to prevent the problem(s) from reoccurring:

Site infrastructure has been removed and will not be replaced.

Volume of Soil Excavated (cubic yards): 10

Disposition of Excavated Soil (attach documentation) ☒ Offsite Disposal Onsite Treatment

☐ Other (specify)

Volume of Impacted Ground Water Removed (bbls):

Volume of Impacted Surface Water Removed (bbls):

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure: ☐ Corrective Actions Completed (documentation attached, check all that apply)

☐ Horizontal and Vertical extents of impacts have been delineated.

☐ Documentation of compliance with Table 915-1 is attached.

☐ All E&P Waste has been properly treated or disposed.

☒ Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No: 23136

☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

## OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Print Name: Gregory Hamilton

Title: Environmental Consultant Date: 06/15/2022 Email: gregory\_hamilton@oxy.com

### Condition of Approval

**COA Type****Description**

0 COA	

### Attachment List

**Att Doc Num****Name**

403076778	SPILL/RELEASE REPORT(I/S)
403077198	ANALYTICAL RESULTS
403081512	FORM 19 SUBMITTED

Total Attach: 3 Files

### General Comments

**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)