

Inspection Photos
Location Name: Mayfield Melton 1
Location ID: 325784



IMG 01
Well sign



IMG 02
Location overview



IMG 03
Unused metal panels



IMG 04
Weeds encroaching pump jack



IMG 05

Rig anchor knocked down



IMG 06

Workover rig sign and metal debris