


Inspection Photos
Location Name: Lila Cummins A2, A3, A4
Location ID: 333762



IMG 01
Well sign



IMG 02
Well sign



IMG 03
Location overview (1/2)

IMG 04
Location overview (2/2)





IMG 05

Weed encroaching A4 pump jack



IMG 06

Weeds encroaching A3 pump jack






IMG 07
Unused stock panel




IMG 08
Unused tarp



IMG 09

Produced water tank sign obstructed by weeds, no listed capacity



IMG 10

Produced water tank is no secured properly, no listed capacity



IMG 11

Produced water tank overgrown by weeds



IMG 12

Rip rap run off