


# Knight B1

Document number 688801150

Date completed 5/27/2022

Remove fluids from containment and clean up stained soil

Remove stained soil from around wellhead



Remove stained soil from around separator piping

