



**Photo taken from the center of the Location shows the excavation around the wellhead. Fence panels completely enclose the area and the slope of the pit is sufficiently gently to allow for wildlife egress**





**Soil pile has been removed from location.**





**Waddles have been repaired or replaced to control sediment.**

