

# Inspection Photos

API: 071-09011

Operator: WAPITI OPERATING LLC

Inspection Date: 6/14/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09011 | Date: 6/14/2022

## Inspection Photos



**Photo 1.** Facing northwest toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09011 | Date: 6/14/2022



## Inspection Photos



**Photo 2.** Facing toward the wellhead. There are noxious weeds around the pumpjack that need to be controlled. Canada thistle, Houndstongue, Mullein.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09011 | Date: 6/14/2022



## Inspection Photos



**Photo 3.** There are noxious weeds along the access road that need to be controlled. The noxious weeds Houndstongue, have already produced seed so the weeds will need to be bagged and removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09011 | Date: 6/14/2022