

**NORTH SHORE EXPLORATION AND PRODUCTION LLC**  
**EVANS-611N93W 29SESE**  
**Location # 313105**



**Battery sign missing API #, No Telephone number for local emergency services (911 where available) and no public road used to access the Tank battery site;**



**Weeds growing inside of tank battery berm.**

**NORTH SHORE EXPLORATION AND PRODUCTION LLC**  
**EVANS-611N93W 29SESE**  
**Location # 313105**



**Weeds growing inside of tank battery berm.**



**Weeds growing inside of tank battery berm.**



**NORTH SHORE EXPLORATION AND PRODUCTION LLC**  
**EVANS-611N93W 29SESE**  
**Location # 313105**



**Weeds growing inside of separator berm**



**Weeds growing inside of separator berm**

**NORTH SHORE EXPLORATION AND PRODUCTION LLC**  
**EVANS-611N93W 29SESE**  
**Location # 313105**



**No API # on well sign.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**NORTH SHORE EXPLORATION AND PRODUCTION LLC**  
**EVANS-611N93W 29SESE**  
**Location # 313105**



**Leak at orifice plate inside of meter shed.**



**Leak at orifice plate inside of meter shed.**

**NORTH SHORE EXPLORATION AND PRODUCTION LLC**  
**EVANS-611N93W 29SESE**  
**Location # 313105**



**Yellow 2" valve outside of metershed is wet from leak around stem.**



**Yellow 2" valve outside of metershed is wet from leak around stem.**



**NORTH SHORE EXPLORATION AND PRODUCTION LLC**  
**EVANS-611N93W 29SESE**  
**Location # 313105**



**Metal tanks between separators NFPA and capacity are faded.**



**Metal tanks between separators NFPA and capacity are faded.**

**NORTH SHORE EXPLORATION AND PRODUCTION LLC**  
**EVANS-611N93W 29SESE**  
**Location # 313105**



**Deadman marker at tank battery has been bent over.**



**Deadman marker at tank battery has been bent over.**