

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2022

Submitted Date:

06/19/2022

Document Number:

701005241**FIELD INSPECTION FORM**Loc ID 302982 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	
Beard, Alyssa		regulatory@foundationenergy.com	
Dolezal, Pat	(970) 332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252205	WELL	PR	02/12/1986	GW	125-06073	BRUDER 1-8	PR

**General Comment:**Routine Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track through pasture		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Metal panels around wellhead, VGS and meter sheds		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment		
Corrective Action:		Date:	
Type: Vertical Separator	# 4		
Comment:	4-Vertical gas separators 50% buried by meter sheds		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:	Shared meter run for (Odell 3-8, 34-8, Shay 33-8 & Bruder 1-8)		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	252205	Type:	WELL	API Number:	125-06073	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Odell 3-8, 34-8, Shay 33-8 & Bruder 1-8)								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701005242	location photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5783291">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5783291</a>