

Inspection Photos
Operator: Arkoma
API: 067-05434
Date: 6/13/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with western wheatgrass, sand dropseed, and scattered sagebrush.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of reference area comprised of open sagebrush shrubland and western wheatgrass field, with James galleta and matte penstemon.