

Inspection Photos
Operator: Simcoe
API: 067-06659
Date: 6/13/2022



Photo 1. View of the project are from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with smooth brome, western wheatgrass, and sand dropseed.



Photo 3. View of the eastern project area from the southeastern corner facing northward. Inset shows Russian olive tree along fenceline that needs to be removed.



Photo 4. View of reference area comprised of open grass pasture with smooth brome, crested wheatgrass, and foxtail barley.