

Inspection Photos
Location Name: Horth R#2
Location ID: 319986



Photo #1 Tanks.

Photo #2 Graffiti on crude tank.

Inspection Photos
Location Name: Horth R#2
Location ID: 319986



Photo #3 loadout line missing bull plug.

Photo #4 Produced water vault.

Inspection Photos
Location Name: Horth R#2
Location ID: 319986



Photo #5 Separator and meter house.

Photo #6 No wildlife protection on open equipment.

Inspection Photos
Location Name: Horth R#2
Location ID: 319986




Photo #7 Graffiti on meter house.

Photo #8 Well head.