







SITE NAME: Howard 1-27/ UP42AM1							DATE: 6/14/2022	REM. PROJECT #:	WEATHER: Sunny, 70 F	
SITE DIRECTIONS: Cr 6 & Cr 21, W 0.1, S into							CLIENT: Oxy			
LEGALS AND LAT/LONG: 40.028881,-104.870956							TASMAN PERSONNEL: Patrick Downs			
SOIL TYPES: Clayey Sand - SC							SURFACE GRADIENT: Northwest			
SOIL SAMPLING							FACILITY INFRASTRUCTURE			
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity	
							Above Ground Storage Tank (AST)		3	
6/14/2022 10:00	AST-B01@6"	3.8	HC Staining	Slight HC Odor	Yes	Lab	Buried or Partially Buried Vessel			
6/14/2022 10:02	AST-B02@3"	0.0	No Staining	No Odor	Yes	N/A	Separator			
6/14/2022 10:04	AST-B03@3"	0.0	No Staining	No Odor	Yes	N/A	Emission Control Device (ECD)			
6/14/2022 10:06	AST-B04@3"	0.0	No Staining	No Odor	Yes	Lab	Dump Line			
6/14/2022 10:08	AST-B05@3"	0.1	No Staining	No Odor	Yes	Lab	Wellhead			
6/14/2022 10:10	AST-B06@3"	0.0	No Staining	No Odor	Yes	N/A	Flowline			
6/14/2022 10:12	BG01@3"	0.0	No Staining	No Odor	Yes	Lab	Other:			
6/14/2022 10:14	BG02@3"	0.2	No Staining	No Odor	Yes	Lab	Soil Loads Removed			
6/14/2022 10:16	BG03@3"	0.0	No Staining	No Odor	Yes	Lab	IMPACTED SOIL IDENTIFIED?			
6/14/2022 10:18	BG04@3"	0.0	No Staining	No Odor	Yes	Lab	ESTIMATED VOLUME OF IMPACTS:			
							Date	Number	CY	
							Total Removed		0	0
							Disposal Facility:			
							Groundwater Recovery			
							DATE GW ENCOUNTERED:		DEPTH:	
							GROUNDWATER IN CONTACT WITH IMPACTED SOIL?			
							LNAPL OR SHEEN OBSERVED ON GW?			
GROUNDWATER SAMPLING							Date		BBLS	
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?				
							Total Removed		0	
							Disposal Facility:			

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	Material:	Volume:	Contents:		
Notes/Conditions:			Notes/Conditions:				

Photographic Log





Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Photographic Log



 <p>Handwritten notes on tank: "Tank Completely Cleaned Out", "Condition = E", "Norm OK", "Cleaned & inspected 5/12/22 R4", "Condition E". Hazard label: "DANGER CONFINED SPACE ENTER BY PERMIT ONLY".</p>			 <p>Release spot</p>				
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:		Volume:		Material:		Volume:	
Contents:				Contents:			
Notes/Conditions:				Notes/Conditions:			

Photographic Log





Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:		Volume:		Material:		Volume:	
Contents:				Contents:			
Notes/Conditions:				Notes/Conditions:			

Photographic Log

							
<p>X BG03@3"</p>			<p>X BG04@3"</p>				
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:		Volume:		Material:		Volume:	
		Contents:				Contents:	
Notes/Conditions:				Notes/Conditions:			