

Inspection Photos
Location Name: Rasmussen TB
Location ID: 470682



Photo 1 TB sign.

Photo 2 TB

Inspection Photos
Location Name: Rasmussen TB
Location ID: 470682



Photo 3 HHS & ECD.



Photo 4 Damaged flow line.

Inspection Photos
Location Name: Rasmussen TB
Location ID: 470682




Photo 5 Damaged flow line.

Photo 6 Damaged flow line.

Inspection Photos
Location Name: Rasmussen TB
Location ID: 470682



Photo 7 Construction fencing around Damaged flow line excavation facing North.

Photo 8 Construction fencing around Damaged flow line excavation facing South.

Inspection Photos
Location Name: Rasmussen TB
Location ID: 470682



Photo 9 Damaged flow line excavation.

Photo 10 Damaged flow line excavation outside of TB berm.