




SITE NAME: DEASON WILLIAMS GU 1 O SA							DATE: 6/13/2022	REM. PROJECT #:	WEATHER: SUNNY HOT 95F
SITE DIRECTIONS: 40.077482, -104.818086							CLIENT: Oxy		
LEGALS AND LAT/LONG: 40.077482, -104.818086							TASMAN PERSONNEL: MATT RIANDA		
SOIL TYPES: Fat Clay - CH							SURFACE GRADIENT: Northwest		
SOIL SAMPLING							FACILITY INFRASTRUCTURE		
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity
							Above Ground Storage Tank (AST)		
06/13/2022 1000	Release Point	NA	Organic staining	Organic Odor	Yes	No	Buried or Partially Buried Vessel		
							Separator		
							Emission Control Device (ECD)		
							Dump Line		
							Wellhead		
							Flowline		
							Other:		
							Soil Loads Removed		
							IMPACTED SOIL IDENTIFIED?		
							ESTIMATED VOLUME OF IMPACTS:		
							Date	Number	CY
							Total Removed		0 0
							Disposal Facility:		
							Groundwater Recovery		
							DATE GW ENCOUNTERED:		DEPTH:
							GROUNDWATER IN CONTACT WITH IMPACTED SOIL?		
							LNAPL OR SHEEN OBSERVED ON GW?		
GROUNDWATER SAMPLING							Date	BBLs	
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?			
							Total Removed		0
							Disposal Facility:		

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			