

Inspection Photos and Issue Report

6/21/2022

Operator: CAERUS PICEANCE LLC #10456

Location ID: 458475

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 458475



Photo 1: Photos taken from the southeast end of the Location, facing west and north. Photos provide overview of the Location. Interim reclamation of the Location has not been completed.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 458475



Photo 2: Photo left show labelling on tank has been installed. Previous inspection observed fluids actively discharging from tank. Photo right shows all impacted soils at the base AND beneath the tank do not appear to have been cleaned/remediated.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 458475



Photo 3: Photo shows tank with inadequate secondary containment has been removed.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 458475



June 22, 2022
39.69457514N 108.12587166W

Photo 4: Photo shows tanks have not been removed from the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 458475



Photo 5: Photos taken from the topsoil stockpile on the north and east end of the Location. Photo shows vegetation on top of the stockpiles are predominantly Undesirable Plant Species. BMPs to protect topsoil stockpile is inadequate.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 458475



Photo 6: Continued from photo 5. Photo shows vegetation establishment on top of the Stockpiles are Undesirable Plant Species.