

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap /12SWNW

Location ID: 456936



Photo #6947 Domestic tap.



Photo #6973 Domestic tap.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap /12SWNW

Location ID: 456936



Photo #6950 Container not labeled.



Photo #6952 Containers open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Domestic Tap /12SWNW

Location ID: 456936



Photo #6955 Containers open ended.



Photo #6954 Domestic tap oderizer and regulators.

