

TEP
RWF 34-12
Location # 324259



location



location

TEP
RWF 34-12
Location # 324259



location



Valve on tank with plug/cap

TEP
RWF 34-12
Location # 324259



Valve on tank with plug/cap



Valve on tank missing cap/plug



TEP
RWF 34-12
Location # 324259



Debris



Lack of stabilization/ compaction



TEP
RWF 34-12
Location # 324259



Lack of stabilization/ compaction. Hard hat in photo



Lack of stabilization/ compaction. Hard hat in photo