

Inspection Photos

June 22, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 324113

Location Name: Burns-66S94W /35SWSE

Inspection Document #: 702800371

Garfield County, CO

SWSE Section 35 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Burns-66S94W /35SWSE
Location ID: 324113



Photo 1. Photo taken from the north shows an overview of the Location.



Inspection Photos
Location Name: Burns-66S94W /35SWSE
Location ID: 324113



Photo 2. Photo taken from the east of the Location shows interim areas dominated by the weedy, native shrub, rubber rabbitbrush.



Photo 3. Photo taken from the east of the Location shows interim areas with a large amount of gravel covering the soil surface which is not found in reference areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800371

Inspection Photos
Location Name: Burns-66S94W /35SWSE
Location ID: 324113



Photo 4. Photo taken from the fill slopes at the southwest of the Location shows an area where vegetation is dominated by noxious weeds (cheatgrass and field bindweed).



Photo 5. Photo taken from the east of the Location shows a portion of the interim area which is dominated by the noxious weed cheatgrass. One musk thistle was also present.

Inspection Photos
Location Name: Burns-66S94W /35SWSE
Location ID: 324113



Photo 6. Photo taken to the southwest of the Location shows the reference area vegetation community is native rangeland. Cheatgrass is uncommon.

