

Inspection Photos

June 22, 2022

Operator: Mustang Resources LLC - #10550

Location ID: 324144

Location Name: Burns-66S94W /35SWSE

Inspection Document #: 702800373

Garfield County, CO

SWSE Section 35 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Burns-66S94W /35SWSE
Location ID: 324144



Photo 1. Photo taken from the north shows an overview of the Location.



Inspection Photos
Location Name: Burns-66S94W /35SWSE
Location ID: 324144



Photo 2. Photo taken from the north of the Location shows western interim areas are well vegetated with crested wheatgrass, a non-native perennial grass.



Photo 3. Photo taken from the south of the Location shows southern interim areas are well vegetated with crested wheatgrass, a non-native perennial grass. However, a dense patch of cheatgrass is present.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800373

Inspection Photos
Location Name: Burns-66S94W /35SWSE
Location ID: 324144



Photo 4. Photo taken from the east of the Location shows eastern interim areas are well vegetated with crested wheatgrass, a non-native perennial grass. Photo also shows cheatgrass is more widespread in the eastern interim areas than in western areas (see Photo 2).



Photo 5. Photo taken from the southeast of the Location shows musk thistle, a Colorado List B noxious weed.

Inspection Photos
Location Name: Burns-66S94W /35SWSE
Location ID: 324144



Photo 6. Photo taken to the west of the Location shows the reference area vegetation community is native rangeland. Cheatgrass is uncommon.

