

Inspection Photos and Issue Report

6/22/2022

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335699

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335699



Photo 1: Photos taken from the south end of the production area. Photos 1-2 provide an overview of the Location from west, northwest, northeast to east.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335699



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335699



Photo 3: Photos provide example of the interim areas. Interim reclamation is “in-process”, however it is noted Operator has used a seed mixture with species not reflective of the adjacent reference area (Barnyard grass, Alfalfa, etc..)

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335699



Photo 4: Photos show example of introduced species observed on Location (alfalfa, orchard grass).

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335699



Photo 5: Photos taken from the TA wells on the east end of the Location. Photo shows uncovered cellars/pipes, and well signs in disarray. Photo also shows wood and trash debris



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335699



Photo 6: Photos taken from the TA wells on the east end of the Location. Photo shows uncovered cellars/pipes, and well signs in disarray. Photo also shows wood and trash debris

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335699



Photo 7: Photo shows string of wells along the upper (wester) section of the working pad. Wells include 045-23878/23874/23873/23876/23881. Unable to find evidence of well 045-23877.