

Inspection Photos
Location Name: Padgett 32-6 4-3
Location ID: 333339



IMG 01
Well sign




IMG 02
Well sign



IMG 03
Location overview




IMG 04
Rig anchor not properly marked



IMG 05

Rig anchor not properly marked



IMG 06

Unused equipment



IMG 07

Tank signs and placards deteriorated and not legible



IMG 08

Tank signs and placards deteriorated and not legible



IMG 09

Unused equipment/ debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources