

Inspection Photos

API: 071-06338

Operator: OGRIS OPERATING LLC

Inspection Date: 6/24/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06338 | Date: 6/24/2022

Inspection Photos



Photo 1. Facing west along the main access road. There has been additional gravel spread along the road and the culverts are maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06338 | Date: 6/24/2022

Inspection Photos



Photo 2. Facing along the access road near the location. There has been additional gravel spread along the road and the culverts are maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06338 | Date: 6/24/2022

Inspection Photos



Photo 3. Facing toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06338 | Date: 6/24/2022