

**COLORADO OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION REPORT**

JAN. 06 1998



<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Str Denver, CO (303)894-1111		 00511124
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION				
API No. 05- 063 - 6254		LEASE NAME: COLMENO INC 14-19 #1		
LOCATION: SWSW19-115-50W		OPERATOR: UPR		
DATE: 12-22-97		INSPECTOR: R. VanSickle		
Insp. Type: ID	Insp. Status: TA	PA: Y <input checked="" type="radio"/> N	Pass/Fail: <input checked="" type="radio"/> P F	Viol.: Y <input checked="" type="radio"/> N
				NOV: Y <input checked="" type="radio"/> N

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210, 604.c(4))	✓	
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)	None	✓
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)	None	
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)	None.	✓
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)	N/A	
<b>General Housekeeping</b> (Rule 603)	OK	
<b>Spills (Oil/Water)</b> (Rule 907)	None	
<b>Bradenhead</b> (Rule 207.b)	—	
<b>Drilling Well/Workover</b> (Rule 317)	—	MAR 12 1998
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)	—	
<b>Miscellaneous</b>	—	

**CORRECTIVE ACTION REQUIRED:** None

Date Corrective Action Required By: \_\_\_\_\_ Date Remedied: \_\_\_\_\_

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.