

Inspection Photos
Location Name: Gary Patrick 1
Location ID: 312019



IMG 01
Well sign



IMG 02
Location overview



IMG 03

Access road erosion channel beginning to form



IMG 04

Erosion channel on southeast edge of location