

Inspection Photos  
Location Name: Sparks B1  
Location ID: 333986



IMG 01  
Well sign




IMG 02  
Location overview





**IMG 03**

**Impacted material at B3 wellhead**



**IMG 04**

**Material has begun to be impacted at B1 wellhead**





**IMG 05**

**Run on from this rip rap channel runs directly onto location**



**IMG 06**

**Unused equipment at B3 wellhead**