

Final Reclamation Inspection

May 24th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 333044

Inspection Document #: 701900388

SESE Section 17 T5N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Hankins 44-17U
Location ID: 333044



Photo 1. 2021 aerial imagery of the well pad and tank battery.

Inspection Photos
Location Name: Hankins 44-17U
Location ID: 333044



Photo 2. Overview photo of the well pad taken at ground level from the eastern edge looking west.

Inspection Photos
Location Name: Hankins 44-17U
Location ID: 333044



Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Hankins 44-17U
Location ID: 333044



Photo 4. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad appears consistent with reference area (see photo 5).

Inspection Photos
Location Name: Hankins 44-17U
Location ID: 333044



Photo 5. Reference area.

Inspection Photos
Location Name: Hankins 44-17U
Location ID: 333044



Photo 6. Overview photo of the tank battery taken at ground level from the southern edge looking north.
Note: Variance form #22020025 is due to be finalized in June 2022.