

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/28/2022

Submitted Date:

06/28/2022

Document Number:

690009459

**FIELD INSPECTION FORM**

Loc ID 302872 Inspector Name: Carlile, Craig On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 47120  
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
 Address: P O BOX 173779  
 City: DENVER State: CO Zip: 80217-

**Findings:**

21 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Oxy		COGCCInspections@Oxy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159570	WELL	PR	01/18/2016	OW	123-40945	CHEESE 37N-28HZ	PR
159571	WELL	PR	01/26/2016	OW	123-40946	CHEESE STATE 26N-21HZ	PR
159572	WELL	PR	04/01/2019	OW	123-40947	CHEESE STATE 26C-21HZ	PR
159573	WELL	PR	07/01/2018	OW	123-40948	CHEESE STATE 1N-21HZ	PR
159574	WELL	PR	12/31/2015	OW	123-40949	CREAM STATE 28C-21HZ	PR
159575	WELL	PR	01/14/2016	OW	123-40950	CHEESE 16N-28HZ	PR
159576	WELL	SI	12/01/2020	OW	123-40951	CREAM 15N-A28HZ	SI
159580	WELL	PR	01/18/2016	OW	123-40955	CHEESE STATE 27N-21HZ	PR
159581	WELL	PR	01/26/2016	OW	123-40956	CHEESE 38N-28HZ	PR
159582	WELL	PR	01/18/2016	OW	123-40957	CHEESE 38C-28HZ	PR
159583	WELL	PR	12/29/2015	OW	123-40958	CREAM STATE 2N-21HZ	PR
159584	WELL	PR	12/28/2015	OW	123-40959	CREAM 15C-28HZ	PR
159585	WELL	PR	01/18/2016	OW	123-40960	CREAM 36N-28HZ	PR
159587	WELL	SI	12/01/2020	OW	123-40962	CREAM STATE 28N-21HZ	SI
159588	WELL	PR	12/31/2015	OW	123-40963	CREAM STATE 2C-21HZ	PR
159589	WELL	PR	12/25/2015	OW	123-40964	CREAM 37N-28HZ	PR
159590	WELL	PR	11/01/2018	OW	123-40965	CREAM 15N-B28HZ	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:			
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

					corrective date
Type: Plunger Lift	# 17				
Comment:					
Corrective Action:		Date:			

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Shared battery services number: 418028				
Corrective Action:		Date:			

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

<b>Inspected Facilities</b>				
Facility ID: <u>159570</u>	Type: <u>WELL</u>	API Number: <u>123-40945</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment: <u>PR</u>				
Corrective Action:				Date:
Facility ID: <u>159571</u>	Type: <u>WELL</u>	API Number: <u>123-40946</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment: <u>PR</u>				
Corrective Action:				Date:
Facility ID: <u>159572</u>	Type: <u>WELL</u>	API Number: <u>123-40947</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment: <u>PR</u>				
Corrective Action:				Date:
Facility ID: <u>159573</u>	Type: <u>WELL</u>	API Number: <u>123-40948</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment: <u>PR</u>				
Corrective Action:				Date:
Facility ID: <u>159574</u>	Type: <u>WELL</u>	API Number: <u>123-40949</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment: <u>PR</u>				
Corrective Action:				Date:
Facility ID: <u>159575</u>	Type: <u>WELL</u>	API Number: <u>123-40950</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment: <u>PR</u>				
Corrective Action:				Date:
Facility ID: <u>159576</u>	Type: <u>WELL</u>	API Number: <u>123-40951</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
<b>Idle Well</b>				
Purpose: <input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____		
Comment: <u>SI</u>				
Corrective Action:				Date: _____
Facility ID: <u>159580</u>	Type: <u>WELL</u>	API Number: <u>123-40955</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	

Facility ID: 159581 Type: WELL API Number: 123-40956 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	

Facility ID: 159582 Type: WELL API Number: 123-40957 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	

Facility ID: 159583 Type: WELL API Number: 123-40958 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	

Facility ID: 159584 Type: WELL API Number: 123-40959 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	

Facility ID: 159585 Type: WELL API Number: 123-40960 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	

Facility ID: 159587 Type: WELL API Number: 123-40962 Status: SI Insp. Status: SI

<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	

<b>Idle Well</b>			
Purpose:	<input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned	Reminder:	_____
Comment:	SI		
Corrective Action:		Date:	_____

Facility ID: 159588 Type: WELL API Number: 123-40963 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	

Facility ID: 159589 Type: WELL API Number: 123-40964 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	

Facility ID: 159590 Type: WELL API Number: 123-40965 Status: PR Insp. Status: PR

<b>Producing Well</b>			
Comment:	PR		
Corrective Action:		Date:	

<b>COGCC Comments</b>		
Comment	User	Date
<a href="#">Routine wellhead inspection.</a>	carlilec	06/28/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690009460	Photos East Pad	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5791153">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5791153</a>
690009461	Photos West Pad	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5791154">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5791154</a>