

Inspection Photos

Location Name: P.J. Jacobucci B-1

Location ID: 318789



Pic 1 wellhead stained soil / mechanical issue by wellhead



Pic 2 pump jack / electric equipment / stained soil / mechanical issue

Inspection Photos

Location Name: P.J. Jacobucci B-1

Location ID: 318789

Jun 16, 2022 at 3:18:22 PM
40.020633,-104.925656
Veld County
COGCC



Pic 3 stained soil next to wellsite needs to be cleaned up