

Final Reclamation Inspection

June 9, 2022

Operator: TOP OPERATING COMPANY - 39560

Location ID: 330147

Inspection Document #: 697504002

Weld County, CO

NWSE Section 8 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LONGMONT #8-10K
Location ID: 330147



Photo 1. Photo taken from the southern location, facing Northeast. Photo illustrates all equipment has been removed from location and final reclamation have been completed. However, there was very little establishment of desirable vegetation.



Photo 2. Photo taken from the location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: LONGMONT #8-10K
Location ID: 330147



Photo 3. Photo taken from the southern location, facing Northwest. See comments under Photo 1.



Photo 4. Photo taken from the central location, facing North. See comments under Photo 1.