

Final Reclamation Inspection

June 9, 2022

Operator: TOP OPERATING COMPANY - 39560

Location ID: 319329

Inspection Document #: 697504004

Weld County, CO

SESW Section 6 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MAYEDA, JOHN Y. #2
Location ID: 319329




Photo 1. Google Earth aerial imagery taken from 9/12/2019. Photo illustrates the well location/access road and the associated offsite tank battery.

Inspection Photos
Location Name: MAYEDA, JOHN Y. #2
Location ID: 319329



Photo 2. Photo taken from the associated offsite tank battery location, facing West. Photo illustrates all equipment has been removed from location and final reclamation have been completed. However, there was very little establishment of desirable vegetation which consisted mostly of weedy annual vegetation.



Photo 3. Photo taken from the western location, facing West. This portion of the location was for Anadarko midstream operations. However, Top Operating was going to try and help to get this properly reclaimed per our rules.



Inspection Photos
Location Name: MAYEDA, JOHN Y. #2
Location ID: 319329



Photo 4. Reference area photo taken north of the location, facing Northeast.