

Final Reclamation Inspection

June 9, 2022

Operator: TOP OPERATING COMPANY - 39560

Location ID: 321290

Inspection Document #: 697504006

Boulder County, CO

NESE Section 36 T3N R69W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: RIDER #1
Location ID: 321290



Photo 1. Photo taken from the western location, facing North. Photo illustrates all equipment has been removed from location and final reclamation has been completed. However, there was desirable vegetation observed but it was patchy and not uniform.



Photo 2. Photo taken from the western location, facing East. See comments under Photo 1.