

Inspection Photos
Location Name: Simon Land and Cattle 27-01 2
Location ID: 306820



IMG 01
Well sign is deteriorated



IMG 02
Location overview





IMG 03

Weeds at produced water tank



IMG 04

Rig anchor not properly marked