

# Inspection Photos

API: 071-08939

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/28/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08939 | Date: 6/28/2022

## Inspection Photos



**Photo 1.** Facing east along the access road. There are a few culverts that are filled in with sediment and stormwater is not properly diverted that need maintenance. (Perhaps handwork can be performed to prevent disturbance.)



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08939 | Date: 6/28/2022

## Inspection Photos



**Photo 2.** Facing east along the access road. There are a few culverts that are filled in with sediment and stormwater is not properly diverted that need maintenance. (Perhaps handwork can be performed to prevent disturbance.)



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08939 | Date: 6/28/2022

## Inspection Photos



**Photo 3.** Facing toward the well site. Vegetation is well established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08939 | Date: 6/28/2022

## Inspection Photos



**Photo 4.** The door is hanging off and needs to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08939 | Date: 6/28/2022