

Final Reclamation Inspection

June 9, 2022

Operator: TOP OPERATING COMPANY - 39560

Location ID: 319067

Inspection Document #: 697504008

Boulder County, CO

NENW Section 31 T3N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: STAMP #31-2C
Location ID: 319067



Photo 1. Photo taken from the northern location, facing South. Photo illustrates all equipment has been removed from location and final reclamation has been completed. Desirable vegetation was observed throughout the disturbance area.



Photo 2. Photo taken from the northern location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: STAMP #31-2C
Location ID: 319067



Photo 3. Photo taken from the northern location, facing East.
See comments under Photo 1.



Photo 4. Photo taken from the central location, facing South.
See comments under Photo 1.

Inspection Photos
Location Name: STAMP #31-2C
Location ID: 319067



Photo 5. Reference photo taken west of location, facing West.