

Construction and Stormwater Inspection

June 17, 2022

Operator: EXTRACTION OIL & GAS INC- #10459

Location ID: 460670

Inspection Document #: 697504012

Weld County, CO

SWSW Section 18 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Blue Paintbrush /Pad
Location ID: 460670



Photo 1. Photo taken from the entrance of location, facing East. Photo illustrates Operator has cleaned up the sediment track out and there were no observed issues during this inspection.



Inspection Photos
Location Name: Blue Paintbrush /Pad
Location ID: 460670



Photo 2. Photo taken from the entrance of location, facing North. Photo illustrates Operator added recycled asphalt as additional BMP.



Inspection Photos
Location Name: Blue Paintbrush /Pad
Location ID: 460670



Photo 3. Photo taken south of the entrance, facing North. Photo illustrates additional tracking device BMPs have been added (additional rock, recycled asphalt and additional roadbase was added to the entire access road). Also, Operator performed the required BMP maintenance.



Inspection Photos
Location Name: Blue Paintbrush /Pad
Location ID: 460670



Photo 4. Photo taken from the western topsoil stockpile, facing East. Operator has seeded and straw crimped mulch into the topsoil.



Photo 5. Photo taken from the southwestern well location, facing East. Photo illustrates a graveled berm BMP has been installed as an additional stormwater BMP.

