

Inspection Photos
Location Name: AM Sprague A1
Location ID: 323132



Colorado Oil & Gas Conservation Commission
40.12547, -104.77045, 4972.1ft, 197°
06/29/2022 12:35:11



Colorado Oil & Gas Conservation Commission
40.12547, -104.77045, 4969.9ft, 30°
06/29/2022 12:35:23

Photo 1 WH sign.

Photo 2 Stained soil has been removed from around the WH.

Inspection Photos
Location Name: AM Sprague A1
Location ID: 323132



Photo 3. Stained soil has been removed from around the WH.

Photo 4 Stained soil has been removed from around the PJ gas engine exhaust.

Inspection Photos
Location Name: AM Sprague A1
Location ID: 323132



Photo 5 Trash has been removed from around the gas engine pressure tank.

Photo 6 TB sign

Inspection Photos
Location Name: AM Sprague A1
Location ID: 323132



Photo 7 TB

Photo 8 Gas Meter Run, ECD and HHS.

Inspection Photos
Location Name: AM Sprague A1
Location ID: 323132



Photo 9 Stained soil has been removed from inside the HHS skid.

Photo 10 Gas Meter Run, card indicates current calibration.