

Inspection Photos
Location Name: Christiansen 1
Location ID: 336288



Photo 1 WH sign.

Photo 2 weeds have been cut around the WH, will need to be monitored.

Inspection Photos
Location Name: Christiansen 1
Location ID: 336288



Photo 3 weeds have been cut around the WH, will need to be monitored.

Photo 4 weeds have been cut around the ancillary equip., will need to be monitored.

Inspection Photos
Location Name: Christiansen 1
Location ID: 336288



Photo 5 TB sign.

Photo 6 weeds have been cut around the TB, they will need to be monitored.