

Inspection Photos

API: 071-09918

Operator: BNL (ENTERPRISE) INC

Inspection Date: 6/29/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09918 | Date: 6/29/2022

Inspection Photos



Photo 1. Facing north along the access road. Sign is posted at access road entrance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 6/29/2022

Inspection Photos



Photo 2. Facing west toward the location. Well sign is posted at the location. The location is fenced and gates have been installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 6/29/2022

Inspection Photos



Photo 3. Facing west toward the well site. There is an open top tank near the well that is full of fluid. Secondary containment will need to be installed per 603.o. or the tank and fluids need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 6/29/2022

Inspection Photos



Photo 4. This photo shows the fluid level of the tank No wildlife protection (netting) is installed to prevent entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 6/29/2022

Inspection Photos



Photo 5. The wellhead has been cover to prevent entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 6/29/2022

Inspection Photos



Photo 6. Facing toward the topsoil pile. It does not appear the entire topsoil pile was seeded as vegetation is not establishing. All unused disturbed areas will need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 6/29/2022

Inspection Photos



Photo 7. Southwest side of the location facing northwest. There are wattles installed along the perimeter swale. The disturbed soils will need to be reclaimed for long term stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 6/29/2022

Inspection Photos



Photo 8. Northwest side of the location facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09918 | Date: 6/29/2022