

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403087335

Date Received:

06/23/2022

Spill report taken by:

FISCHER, ALEX

Spill/Release Point ID:

482283

**SPILL/RELEASE REPORT (SUPPLEMENTAL)**

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

**OPERATOR INFORMATION**

Name of Operator: CAERUS PICEANCE LLC	Operator No: 10456	<b>Phone Numbers</b>
Address: 1001 17TH STREET #1600		Phone: (970) 778-2314
City: DENVER State: CO Zip: 80202		Mobile: (970) 778-2314
Contact Person: Jake Janicek		Email: jjanicek@caerusoilandgas.com

Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

**INITIAL SPILL/RELEASE REPORT**

Initial Spill/Release Report Doc# 403082229

Initial Report Date: 06/16/2022 Date of Discovery: 06/15/2022 Spill Type: Recent Spill

**Spill/Release Point Location:**

QTRQTR SENW SEC 7 TWP 8S RNG 95W MERIDIAN 6

Latitude: 39.378744 Longitude: -108.037383

Municipality (if within municipal boundaries): County: GARFIELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

**Reference Location:**

Facility Type: OIL AND GAS LOCATION  Facility/Location ID No 311684

Spill/Release Point Name:  Well API No. (Only if the reference facility is well) 05- -

No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): Unknown

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

Has the subject Spill/Release been controlled at the time of reporting? Yes

**Land Use:**

Current Land Use: NON-CROP LAND Other(Specify): \_\_\_\_\_

Weather Condition: Sunny

Surface Owner: FEDERAL Other(Specify): \_\_\_\_\_

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

The air team conducted a methane detection fly over. The fly over detected some methane on the 7F pad. Upon receiving this data the LDAR inspector went to investigate. He arrived on location and detected gas around the separators with his FLIR camera. Because this location is in the H2S area the decision was made to shut in the location and let the H2S team investigate the matter in the morning. No H2S levels were seen on the LDAR inspectors personal gas monitor. The operators investigation the next morning found the sales line down stream of the separator did not pass pressure test. As a result the location was shut in.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
6/16/2022	CPW	Taylor Elm	-	Sent Form 19
6/16/2022	Garfield County	Kirby Wynn	-	Sent Form 19
6/16/2022	BLM	Doug Jones	-	Sent Form 19
6/16/2022	COGCC	Alex Fischer	-	Sent Form 19
6/16/2022	BLM	Jim Byers	970-319-2535	Notified via phone

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

No  Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: \_\_\_\_\_ Public Water System: \_\_\_\_\_  
 Residence or Occupied Structure: \_\_\_\_\_ Livestock: \_\_\_\_\_  
 Wildlife: \_\_\_\_\_ Publicly-Maintained Road: \_\_\_\_\_

No  Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

No  Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No  Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)  
 Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_  
 Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_  
 Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_  
 Was there damage during excavation? \_\_\_\_\_  
 Was CO 811 notified prior to excavation? \_\_\_\_\_

No  Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_



The Depth to Groundwater value listed above is an estimate based on topography. There are no water wells in close proximity to compare with.

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

- Basis for Closure:
- Corrective Actions Completed (documentation attached, check all that apply)
    - Horizontal and Vertical extents of impacts have been delineated.
    - Documentation of compliance with Table 915-1 is attached.
    - All E&P Waste has been properly treated or disposed.
  - Work proceeding under an approved Form 27 (Rule 912.c).  
Form 27 Remediation Project No: \_\_\_\_\_
  - SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

### OPERATOR COMMENTS:

The failure point has not been identified therefore photo documentation and an updated GPS point cannot be presented yet.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Jake Janicek  
Title: EHS Specialist Date: 06/23/2022 Email: jjanicek@caerusoilandgas.com

### Condition of Approval

#### COA Type

#### Description

0 COA

### Attachment List

<u>Att Doc Num</u>	<u>Name</u>
403087335	SPILL/RELEASE REPORT(SUPPLEMENTAL)
403087339	TOPOGRAPHIC MAP
403093799	FORM 19 SUBMITTED

Total Attach: 3 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	Comply with outstanding COAs.	06/30/2022

Total: 1 comment(s)