

**Inspection Photos**  
**Location Name: Leggett 1-5H**  
**Location ID: 428225**



**Photo 1 – Heater Treater and Gas Meters**




**Photo 2 – Pumping Unit**



**Inspection Photos**  
**Location Name: Leggett 1-5H**  
**Location ID: 428225**



**Photo 3 – Unmarked Riser at Wellhead**




**Photo 4 – Wellhead – Unmarked Riser**



**Inspection Photos**  
**Location Name: Leggett 1-5H**  
**Location ID: 428225**



**Photo 5 – ECD and Flare**



**Photo 6 – Weeds**

**Inspection Photos**  
**Location Name: Leggett 1-5H**  
**Location ID: 428225**



**Photo 7 – Weeds in Interim Reclamation Area**



**Photo 8 – Weeds in Interim Reclamation Area**



**Inspection Photos**  
**Location Name: Leggett 1-5H**  
**Location ID: 428225**



**Photo 9 – Weeds in Interim Reclamation Area**



**Photo 10 – Weeds in Interim Reclamation Area**

**Inspection Photos**  
**Location Name: Leggett 1-5H**  
**Location ID: 428225**



**Photo 11 – Weeds in Interim Reclamation Area**



**Photo 12 – Labels Updated**



Inspection Photos  
Location Name: Leggett 1-5H  
Location ID: 428225



Photo 13 – Labels Updated



Photo 14 – Tank Battery Sign

