

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 1 – Wellhead



Photo 2 – West Side of Gear Box

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 3 – West Side of Gear Box




Photo 4 – East Side of Gear Box



Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 5 – East Side of Gear Box



Photo 6 – East Side of Gear Box

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 7 – East Side of Gear Box



Photo 8 – East Side of Gear Box



Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 9 – ECD and Flare



Photo 10 – Heater Treater and Gas Meters

Inspection Photos
Location Name: Buchner 2-2H
Location ID: 431634



Photo 11 – Tank Battery



Photo 12 – Tank Battery Sign