

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Photo 1 – Tank Battery Signs

Photo 2 – Tank Battery

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327




Photo 3 – 2-3: Weeds and Unused Tubing

Photo 4 – 2-3: Weeds and Stained Soil at Exhaust

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327




Photo 5 – 2-3: Stained Soil at Engine

Photo 6 – 2-3 Wellhead

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Photo 7 – 2-6 Pumping Unit

Photo 8 – 2-6: Debris at Engine

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Photo 9 – 2-6: Stained Soil at Exhaust

Photo 10 – 2-1: Debris at Engine

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Photo 11 – 2-1: Stained Soil at Wellhead

Photo 12 – 2-1: Stained Soil at Wellhead