

Interim Reclamation and Stormwater Inspection

June 16, 2022

Operator: CCRP OPERATING INC - #10665

Location ID: 441995

Inspection Document #: 697503541

Weld County, CO

NWNW Section 24 T12N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources_S

Inspection Photos

Location Name: Grynberg Stateline Federal /24-12-65-4 Pad

Location ID: 441995



Photo 1. Photo taken from eastern interim reclamation area, facing North. Photo illustrates the establishment of desirable plant species; however, the plant cover is not reflective of reference areas and the establishment of cheatgrass has increased since the previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503541

Inspection Photos

Location Name: Grynberg Stateline Federal /24-12-65-4 Pad

Location ID: 441995



Photo 2. Photo taken from southeastern interim reclamation area, facing West. Photo illustrates cheatgrass is the dominant vegetative cover along the southern fill slope with some desirable vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503541

Inspection Photos

Location Name: Grynberg Stateline Federal /24-12-65-4 Pad

Location ID: 441995



Photo 3. Photo taken from southeastern interim reclamation area, facing East. Photo illustrates cheatgrass is the dominant vegetative cover along the southeastern interim area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503541

Inspection Photos

Location Name: Grynberg Stateline Federal /24-12-65-4 Pad

Location ID: 441995



Photo 4. Photo taken from eastern perimeter of location, facing South. Photo illustrates cheatgrass was not observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503541

Inspection Photos

Location Name: Grynberg Stateline Federal /24-12-65-4 Pad

Location ID: 441995



Photo 5. Photo taken from eastern interim reclamation area, facing West. Photo the well pad has been stabilized and there does not appear to be any sediment movement via wind erosion.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503541