

# Final Reclamation Inspection

May 26th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 332073

Inspection Document #: 701900403

SWNE Section 30 T6N R63W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: J & L Farms 32-30  
Location ID: 332073



**Photo 1.** 2021 aerial imagery of the well pad and tank battery.



Inspection Photos  
Location Name: J & L Farms 32-30  
Location ID: 332073



**Photo 2.** Overview photo of the well pad taken at ground level from the western edge looking east.




Inspection Photos  
Location Name: J & L Farms 32-30  
Location ID: 332073



**Photo 3.** Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.



Inspection Photos  
Location Name: J & L Farms 32-30  
Location ID: 332073



**Photo 4.** Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: Plant establishment and recontouring issues observed indicated by the red arrows.



Inspection Photos  
Location Name: J & L Farms 32-30  
Location ID: 332073



**Photo 5.** Overview photo of the tank battery taken at ground level from the western edge looking east.



Inspection Photos  
Location Name: J & L Farms 32-30  
Location ID: 332073



**Photo 6.** Cardinal photos taken from the middle of the tank battery. Left photo facing north, right photo facing east.



Inspection Photos  
Location Name: J & L Farms 32-30  
Location ID: 332073



**Photo 7.** Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: It appears that the operator has performed final reclamation activities at the tank battery however, no desirable species were observed. Tank battery does not appear consistent with tank battery reference area. (see photo 8).



Inspection Photos  
Location Name: J & L Farms 32-30  
Location ID: 332073



**Photo 8.** Tank battery reference area.