

Inspection Photos

Location Name: 70 RANCH LAURA-65N63W /20SWSE

Location #: 332433




Photo #1

70 Ranch Laura 34-20 (05-123-22293) Wellsite

Temporarily Abandoned | TA



Photo #2

70 Ranch Laura 13-20, 14-20, 24-20, 34-20, CSW 20

Battery site

Inactive | Shut-down

Inspection Photos

Location Name: 70 RANCH LAURA-65N63W /20SWSE

Location #: 332433



Colorado Oil & Gas Conservation Commission
Weld County
+40.384380 -104.465874
330° NW
2022-06-29 14:22

Photo #3

70 Ranch Laura 13-20, 14-20, 24-20, 34-20, CSW 20

Battery site

Inactive | Shut-down

Tanks: SE corner



Colorado Oil & Gas Conservation Commission
Weld County
+40.384351 -104.465746
65° NE
2022-06-29 14:23

Photo #4

70 Ranch Laura 13-20, 14-20, 24-20, 34-20, CSW 20

Battery site

Inactive | Shut-down

Separator, ECD

Inspection Photos

Location Name: 70 RANCH LAURA-65N63W /20SWSE

Location #: 332433



Photo #5

70 Ranch Laura 13-20, 14-20, 24-20, 34-20, CSW 20

Battery site

Inactive | Shut-down

Battery sign



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources