


# Inspection Photos

Location Name: 70 RANCH LAURA-65N63W /20SESW

Location #: 332694



**Photo #1**

**70 Ranch Laura 24-20 (05-123-22288) Wellsite**

**Temporarily Abandoned | TA**



**Photo #2**

**70 Ranch Laura 14-20 (05-123-22292) Wellsite**

**Temporarily Abandoned | TA**

## Inspection Photos

Location Name: 70 RANCH LAURA-65N63W /20SESW

Location #: 332694



**Photo #3**

70 Ranch CSW 20 (05-123-24031) Wellsite

**Temporarily Abandoned | TA**



**Photo #4**

70 Ranch Laura 13-20, 14-20, 24-20, 34-20, CSW 20

Battery site

**Inactive | Shut-down**

## Inspection Photos

Location Name: 70 RANCH LAURA-65N63W /20SESW

Location #: 332694



Colorado Oil & Gas Conservation Commission  
Weld County  
+40.384380 -104.465874  
330° NW  
2022-06-29 14:22

### Photo #3

70 Ranch Laura 13-20, 14-20, 24-20, 34-20, CSW 20

Battery site

Inactive | Shut-down

Tanks: SE corner



Colorado Oil & Gas Conservation Commission  
Weld County  
+40.384351 -104.465746  
65° NE  
2022-06-29 14:23

### Photo #4

70 Ranch Laura 13-20, 14-20, 24-20, 34-20, CSW 20

Battery site

Inactive | Shut-down

Separator, ECD

# Inspection Photos

Location Name: 70 RANCH LAURA-65N63W /20SESW

Location #: 332694



## Photo #5

70 Ranch Laura 13-20, 14-20, 24-20, 34-20, CSW 20

Battery site

Inactive | Shut-down

Battery sign

