

## Inspection Photos

Location Name: CHEVRON USA INC WILSON CREEK UNIT-62N94W /4NWSE

Location ID: 316060



Photo #7050 from entrance to location.



Photo #7052 from entrance to location.

## Inspection Photos

Location Name: CHEVRON USA INC WILSON CREEK UNIT-62N94W /4NWSE

Location ID: 316060



**Photo #7053 Work over rig fire.**



**Photo #7054 Workover rig fire.**

## Inspection Photos

Location Name: CHEVRON USA INC WILSON CREEK UNIT-62N94W /4NWSE

Location ID: 316060



Photo #7055 Workover rig fire.



Photo #7056 Nearest production equipment to workover rig and accumulator.

## Inspection Photos

Location Name: CHEVRON USA INC WILSON CREEK UNIT-62N94W /4NWSE

Location ID: 316060



Photo #7058 Workover rig and tank battery stair case.



Photo #7057 Tank battery.