

Inspection Photos

API: 055-06285

Operator: CAPTUREPOINT LLC

Inspection Date: 7/1/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06285 | Date: 7/1/2022

Inspection Photos



Photo 1. Facing west toward the access road. There are noxious weeds along the road that need to be controlled. Red arrow → Scotch thistle



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06285 | Date: 7/1/2022

Inspection Photos



Photo 2. Facing toward the location. There are noxious weeds at the location that need to be controlled. Red arrow → Scotch thistle



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06285 | Date: 7/1/2022

Inspection Photos



Photo 3. Well sign has been updated to reflect current Operator.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06285 | Date: 7/1/2022