



Inspection Photos
Location Name: Huber-Lobato 1-26
Location ID: 326147



IMG 01
Well sign



IMG 02
Location overview




IMG 03

Unused equipment at pump jack




IMG 04

Rig anchor head and marker are trash



IMG 05

Impacted material at generator muffler hose



IMG 06

Impacted material at wellhead



IMG 07

Construction debris on southeast corner of location